201 Louisa St.	LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	PREVIOUSLY LEAD?	PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	NOTES ON BASIS OF MATERIAL CLASSIFICATION
316 Jourisa St. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 514 Jourisa St. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 514 Jourisa St. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 502 Jourisa St. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 502 Jourisa St. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 514 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 514 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 514 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 519 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 519 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 519 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 519 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 517 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 507 Fritite Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 507 Fritite Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 507 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 507 Hernette Ave. C N C Otherdescribe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 5	203 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
\$10 Louis St. C N C Other-describe in notes Y Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes Y Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 for fritted was C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 for fritted was C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 for fritted was C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V Installed affer lead ban V Visual, entire system was put in post 1978 follows St. C N N C Other-describe in notes V	201 Louisa St.				Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
S44 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 602 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 602 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 601 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 613. Henriette Ave. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 712 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 712 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 712 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 712 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 714 Louis St. C N C Other-describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 716 Louis St. C N C Other-describe in notes Y In	316 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
602 Louisa St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 605 Louisa St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 605 Louisa St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 519 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 519 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 519 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 519 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 519 Third Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 519 Tritice Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 510 Tritice Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 510 Tritice Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 517 Tritice Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 506 Henriette	510 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
602 Louis St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 511 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 513 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 520 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 520 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 520 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 712 Louis St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 727 Louis St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 728 Comment of the system was put in post 1978 728 Comment of the system was put in post 1978 729 Comment of the system was put in post 1978 720 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 721 Louis St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 722 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 723 Sarah St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 724 Louis St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 725 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 725 Herniette Ave. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 726 Louis St. C N C Other-describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 727	514 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
606 Louks St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 520 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 722 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 722 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 721 Louisa S	602 Louisa St.		N		Other - describe in notes	Y	Installed after lead ban		Visual, entire system was put in post 1978
\$11 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$20 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$20 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$197 th Alley C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 \$100 Henriette Ave. \$C N C Other - describe in notes Y I	602 Louisa St.		N		Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
5.91 Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 5.19 Print Alley C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 7.12 Louisa St. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 7.12 Louisa St. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Print Alley C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Print Alley C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Print Alley C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Print Alley C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire system was put in post 1978 SOF Herniette Ave. C N C Other - describe in notes V Installed after lead ban V Visual, entire sy	606 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
\$20 Interlitet Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 1978 Allay C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 508 7th Allay C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 508 7th Allay C N C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 713 5arah St. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 713 5arah St. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 713 5arah St. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 506 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 517 Fritie Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 517 Fritie Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in post 1978 517 Fritie Ave. C N C Other - describe in notes V Installed after lead ban Y Visual, entire system was put in po	511 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
5.97 Pth Alley C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Pth Alley C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Pth Alley C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 507 Pth Pth Alley C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Pth Alley C N C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Pth Pth Pth Alley C N N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Pth	519 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
722 Louis St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 SO7 Fritzie Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 SO7 Fritzie Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 T18 Louis St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 T18 Louis St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 T18 Louis St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 SO7 Horizie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was p	520 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
508 7th Alley C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 713 Sarah St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 714 So Planniette Ave. C N C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 714 So Planniette Ave. C N C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 714 So Planniette Ave. C N C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 714 So Planniette Ave. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9	519 7th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Sof Fritzie Ave. C N C Other -describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	712 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
7.33 Sarah St. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 506 Henriette Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 508 Henriette Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 508 Henriette Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 507 Henriette Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 716 Louisa St. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 716 Louisa St. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 517 Fritzie Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 517 Fritzie Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 517 Fritzie Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 517 Fritzie Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 517 Fritzie Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 510 Mina Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 510 Mina Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 510 Mina Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 510 Mina Ave. C. N. C. Other-describe in notes Y. Installed after lead ban Y. Visual, entire system was put in post 1978 510 Mina Ave. C. N. C. Other-describe in notes Y. Installed after lead b	508 7th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
506 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Lo	507 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
502 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 716 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 717 Fritzie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 710 Mina Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 719 Louisa St	713 Sarah St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
508 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 507 Henriette Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 717 Fitzle Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 717 Fitzle Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 718 718 719 719 719 719 719 719 719 719 719 719	506 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
507 Henriette Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 517 Fritzie Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 820 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 820 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 820 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 1500 Mira Ave. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y installed after lead ban Y Visual, entire system was put in post 1978 1978 1978 1978 1978 1978 1978 1978	502 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 718 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 807 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 808 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 808 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C O	508 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
78 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 820 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 820 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1980 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C	507 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
517 Fritzie Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 804 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 809 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 510 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 519 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1978 1979 1979 1979 1979 1979 1979	716 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
804 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 820 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 100 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 100 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 100 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 100 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 100 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 100 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N	718 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
820 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 510 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 519 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 519 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 1018 1018 1018 1018 1018 1018 10	517 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
900 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 S10 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 919 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 91000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 91000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 91000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 91000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9178 Asa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9188 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 91978 9178 Asa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9188 Asa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 91978 9178 Asa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9189 9178 Asa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9189 9178 Asa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 9189 9189 9199 9199 9199 9199 9199 919	804 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
510 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 508 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1013 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1014 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post	820 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
508 Mira Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 519 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1014 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1016 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1017 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post	900 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
918 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 197	510 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
519 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1014 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1016 After lead ban Y Visual, entire system was put in post 1978 1017 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1016 After lead ban Y Visual, entire system was put in	508 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1013 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1014 Coulisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1015 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1016 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1017 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave.	918 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1000 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1018 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1019 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in pos	519 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 517 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 518 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 505 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 505 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	1000 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1008 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 517 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 518 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	1000 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1012 Louisa St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 517 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 518 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 505 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	1008 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
517 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 518 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	1008 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
518 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 517 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	1012 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 505 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 517 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	517 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
503 Rosa Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 517 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	518 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 C Installed after lead ban Y Visual, entire system was put in post 1978 C Installed after lead ban Y Visual, entire system was put in post 1978 C Installed after lead ban Y Visual, entire system was put in post 1978 C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	503 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
502 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 Installed after lead ban Y Visual, entire system was put in post 1978 Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 Installed after lead ban Y Visual, entire system was put in post 1978 Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	503 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
504 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 917 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	502 Lulu Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
515 Lulu Ave. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978 917 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	502 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
917 Sarah St. C N C Other - describe in notes Y Installed after lead ban Y Visual, entire system was put in post 1978	504 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
, , , , ,	515 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
500 Mira Ave C N C Other - describe in notes Y Installed after lead han Y Visual entire system was nut in nost 1978	917 Sarah St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
of the describent notes in motioned after read but in visual, entire system was put in post 1576	500 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

500 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
503 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
821 Sarah St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
302-308 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
302-308 Henriette Ave	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
305 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
701 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
709 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
717 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
717 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
721 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
735 Dyer St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
743 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
743 Dyer St.	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
744 Dyer St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
744 Dyer St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
728 Dyer St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
205 Henriette Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
607 USH 141N	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
607 USH 141N	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
216 Henriette Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	
707 Angle St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
	C		С				Y	Visual, entire system was put in post 1978
Triangle Park Angle St.		N		Other - describe in notes	Y	Installed after lead ban		Visual, entire system was put in post 1978
711 Angle St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
711 Angle St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
713-715-717 USH 141N	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
805 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
803 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
809 USH 141N	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
807 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
901 USH 141N	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
905 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
907 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
913 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
915 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
917 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
706 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
129 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
119 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
115 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
601 Wolf St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
604 Wolf St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
6 Richlen Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
417 Hattie St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
407 Hattie St.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
2 E. Clover St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
2 E. Clover St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
401 Julie St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
17 E. Clover St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
11 Richlen Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
II NICHEH AVE.	C	IN	C	Other - describe in notes	ſ	mistaneu arter ledu barr	Г	visual, elittie system was put ili post 1978

414 Jacquelyn St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
22 E. Richlen Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
106 Richlen Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
10E Richlen Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
101 E. Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
101 E. Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
14 East Bldg Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
14 East Bldg Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
W7856 CTH W	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
104 West Bldg Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
104 West Bldg Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
104 (Irrig) Henriette Ave	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
519 (Supita) USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
515 (Clinic) USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
511 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
407 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
315 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
315 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
305 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
305 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
251 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
247 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
201 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
117 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
107 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
105 USH 141N	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
7 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
13 -McDonalds USH 141S	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
13 - Shell USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
13 -Car Wash USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
111-115 USH 141S	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
105 USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
219 South Ave	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
400 South Ave	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
400 South Ave	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
210 Oak St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Concessions South Ave	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
Irr South Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
Irr South Ave.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
400 South Ave	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
4 Oak St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
Oak St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
202 Oak St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
214 Oak St.	C	N	С		Y		Y	
214 Oak St.	C	N	C	Other - describe in notes Other - describe in notes	Y	Installed after lead ban Installed after lead ban	Y	Visual, entire system was put in post 1978
								Visual, entire system was put in post 1978
220 Pine Ave.	С	N	C C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
215 Hall Ave.	С	N		Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
221 Hall Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
214 Pine Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
211 Pine Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
217 Pine Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

302 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
305 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
305 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
329 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
300 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
414 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
300 Car Wash Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
423 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Park Restroom Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
420 Irrig Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
117 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
602 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
610 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
125 Finnelli Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
510 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
600 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
115 Finnelli Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
418 NWTC USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
410 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
412 USH 141S	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
218 USH 141S	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
218 USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
216 USH 141S	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
212 USH 141S	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
212 USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
212 USH 141S	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
212 USH 141S	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
212 USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
210 USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
114 USH 141S	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	
114 USH 141S	C		C		Y		Y	Visual, entire system was put in post 1978
110 USH 141S		N		Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
104 USH 141S	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
125 South Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
106 South Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
114 South Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
122 South Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
10 USH 141S	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
10 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
4 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
2-6 USH 141S	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
6 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
10 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
10 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
112 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
214 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
404 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
404 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
410 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
410 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

504 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
516 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
610 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
608616 USH 141N	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
402 Craig St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
506 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
502 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
508 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Fire Hydrant Fire Hydrant	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
315 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
608 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
608 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
614 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
708 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
701 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Youth Basebal Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Youth Basebal Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
702 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
701 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
719 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
719 Park Ave (Irrig)	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
300 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
301 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
251 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
805 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
806 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
808 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
807 Park Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
305 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
307 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
310 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
400 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
400 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
710 Hall Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
711 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
401 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
401 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
804 Hall Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
807 Hall Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
808 Hall Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
402 George St.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
401 George St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
407 George St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
407 George St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
411 George St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
809 Anderson Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
717 Anderson Ave.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
717 Anderson Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
709 Anderson Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
701 Anderson Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
615 Anderson Ave.	C	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
oto Anderson Ave.		IN	C	Other - describe in notes	1	ilistalleu arter leau bari	ľ	visual, entire system was put in post 1978

616 Anderson Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
622 Anderson Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
712 Anderson Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
712 Anderson Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
504 Wilbert St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
501 Wilbert St.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
913 Anderson Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
501 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
504 F.J. St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
504 F.J. St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1005 Main Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1009 Main Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1009 Main Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
401 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
401 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
417 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
421 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
600 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
604 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
607 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
608 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
608 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
611 Main Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
612 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
615 Henriette Ave	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
702 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
713 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
710 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
712 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
714 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
801 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
805 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Irrig South parking lot	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
Irrig South parking lot	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
903 Main Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
903 Main Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
903 Main Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
904 Main Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
905 Main Ave.	C	N N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
901 Henriette Ave	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
903 Henriette Ave	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
903 Henriette Ave	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
903 Henriette Ave	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
902 Henriette Ave.	C	N N	C	Other - describe in notes Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
	C	N N	C	Other - describe in notes Other - describe in notes	Y	Installed after lead ban	Y	, , , , ,
902 Henriette Ave.	C	N N	C		Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
808 Henriette Ave.				Other - describe in notes	Y		Y	Visual, entire system was put in post 1978
808 Henriette Ave.	C C	N	С	Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
808 Henriette Ave.		N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
800 Henriette Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
716 Henriette Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
716 Henriette Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978

710 Henriette Ave. Irrig	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
708 Henriette Ave	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
700 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
700 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
703-705 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
622 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
610 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
606 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
606 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
611 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
607 Louisa St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
718 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
718 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
718 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
700 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
711 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
705 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
704 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
707 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
711 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
712 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
714 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
800 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
806 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
806 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
810 Wilbert St.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
811 Wilbert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
801 Fritzie Ave.	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
805 Fritzie Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
809 Fritzie Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
806 Fritzie Ave.	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
806 Fritzie Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
814 Fritzie Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
808 George St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
814 8th Alley	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
801 George St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
801 George St. (Irrig)	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
801 George St. (ITTIG)	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
713 George St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
713 George St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
914 Fritzie Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
914 Fritzie Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
909 Mira Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
913 Mira Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	
913 Mira Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
							Y	
904 F.J. St. 904 F.J. St.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
	C		C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
916 Mira Ave.		N		Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
906 Mira Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
900 Mira Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
901 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

816 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
810 8th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
810 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
810 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
800 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
716 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
717 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
718 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
710 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
706 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
707A Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
707B Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
707A & 707B Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
715 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1001 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
618 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
918 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
919 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
915 Hall Hay St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
702 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
706 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
712 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
711 Mira Ave.	С	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
709 Mira Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
707 Mira Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
813 Hall Hay St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
813 Hall Hay St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
704 8th Alley	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
607 Lulu Ave.	С	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
602 Lulu Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1017 Louisa St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
609 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ Υ	Visual, entire system was put in post 1978
1012 Hall Hay St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1015 Hall Hay St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1015 Hall Hay St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1101 Hall Hay St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1116 Wilbert St.	С	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
North Cem Rosa Ave.	С	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
806 Mausoleum Lulu Ave.	С	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
Cemetery Cemetery	С	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
903 Lulu Ave.	С	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
916 F.J. St.	С	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
	С	N N	С		Y	Installed after lead ban	Y	
1006 F.J. St. 1014 F.J. St.	C	N N	C	Other - describe in notes	Y		Y	Visual, entire system was put in post 1978
				Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
916 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1108 F.J. St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1114 F.J. St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
911 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
909 North Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
915 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
906 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

912 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Fire Station Fire Hydrant	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1001 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
701 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1005 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1005 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1006 Henriette Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1010 Henriette Ave	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1010 Henriette Ave	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1010 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1000 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
515-517 Left Foot Lake Rd.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1312 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
604 Funk St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1320 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1401 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1400 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
607 Funk St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
704 Funk St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
806 Funk St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
812 Funk St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
813 Funk St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1418 Kloppman St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1521 Kloppman St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1501 Kloppman St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1333 Kloppman St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1330 Kloppman St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
820 East Kloppman St	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
605 East Kloppman St	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
606 East Kloppman St	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
705 Funk St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1410 Kaby Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1415 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1420 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1516 Kaby Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1419 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Υ Υ	Visual, entire system was put in post 1978
1503 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1509 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1509 Kaby Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1513 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1517 Kaby Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1518 Kaby Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1607 Kaby Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
819 Kloppman St.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	
1607 Kaby Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
901 Kloppman St.	C	N N	C		Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
• • • • • • • • • • • • • • • • • • • •	C	N N	С	Other - describe in notes	Y		Y	Visual, entire system was put in post 1978
904 Kloppman St.				Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
906 Kloppman St.	С	N	С	Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
1606 Kloppman St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
806 Kloppman St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1616 Kaby Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

1617 Kaby Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
606 Cox St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1615 Kaby Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
608 Cox St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
All Apts. Kaby Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1616 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
W8490 Germantown Lane	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
Irrig Germantown Lane	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1609 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1607 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1605 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1605 & 1607 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1515 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1512 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1510 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1420 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1417 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1417 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1410 Main Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1002 7th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1008 7th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1010 7th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1009 7th Alley	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
715 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
801 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
805 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1004 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1006 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1010 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1014 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1013 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1023 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1025 Fritzie Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
901 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1104 Mira Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1111 Mira Ave.	С	N	C	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
902 Robert St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
904 Robert St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1010 Mira Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
901 F.J. St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
811 F.J. St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
911 F.J. St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1004 Lulu Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1011 F.J. St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1011 F.J. St.	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
1006 Lulu Ave.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1012 Lulu Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1012 Edit Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1106 Lulu Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1122 Lulu Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1210 Lulu Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	
1210 Luiu Ave.	C	IN	L	Other - describe in notes	ſ	nistaneu arter leau bari	ľ	Visual, entire system was put in post 1978

1205 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1201 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
909 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
936 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1013 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1013 Lulu Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1010 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1015 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1017 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1101 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1107 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1115 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1009 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1009 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1009 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1015 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1120 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1102 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1018 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1015 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1109 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1112 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1116 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1115 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1216 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1205 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1219 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1219 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1218 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1218 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1221 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1221 Rosa Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1221 Rosa Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1221 Rosa Ave.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1310 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1310 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1314 Rosa Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1316 Rosa Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1318 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1317 Rosa Ave.	C	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1410 Rosa Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1415 Rosa Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1413 Rosa Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1419 Rosa Ave.	C	N N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1419 Rosa Ave.	С	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1620 Duke Ln.	C	N	С		Y	Installed after lead ban	Y	
1618 Duke Lane	С	N N	С	Other - describe in notes Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
	C	N N	C		Y		Y	Visual, entire system was put in post 1978
1621 Duke Lane		N N		Other - describe in notes		Installed after lead ban	Y	Visual, entire system was put in post 1978
1615 Duke Lane	С		С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1611 Duke Lane	C C	N	C	Other - describe in notes	Y	Installed after lead ban		Visual, entire system was put in post 1978
1601 Duke Lane	C	N	C	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978

1310 Kenny Dr.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1323 1st Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1323 1st Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1328 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1327 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1329 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1320 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1219 1st Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1209 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1205 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1205 Electra Dr.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1113 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1110 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1105 North Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1201 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1201 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1309 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
910 1st Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
920 1st Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
920 1st Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1210 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1215 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1304 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1304 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1309 Robert St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1315 Robert St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1303 Robert St.	C	N	C	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
1113 1st Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
1210 Electra	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1110 1st Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1200 1st Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1212 1st Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1309 1st Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1310 1st Ave.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1310 1st Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1310 1st Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1318 1st Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1410 Kenny Dr.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1325 2nd Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1314 2nd Ave.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1410 Gene St.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1217 2nd Ave.	C	N N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1409 Electra	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	
1206 2nd Ave.	C	N	C		Y		Y	Visual, entire system was put in post 1978
1112 2nd Ave.	C	N N	С	Other - describe in notes Other - describe in notes	Y	Installed after lead ban Installed after lead ban	Y	Visual, entire system was put in post 1978
	C							Visual, entire system was put in post 1978
1112 2nd Ave.		N N	C C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1117 2nd Ave.	С		-	Other - describe in notes	Y	Installed after lead ban		Visual, entire system was put in post 1978
1315 Electra	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1201 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1109 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1111 2nd Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

1405 1407 2 14	•		•	0.1 1 11			.,	\" \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
1105-1107 2nd Ave.	C C	N	C C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1017 2nd Ave.		N		Other - describe in notes		Installed after lead ban	Y	Visual, entire system was put in post 1978
1010 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	-	Visual, entire system was put in post 1978
1012 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1102 2nd Ave.	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1317 F.J. St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1004 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1316 F.J. Street	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
922 2nd Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1413 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1414 F.J. St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
916 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
907 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1317 George St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
908 2nd Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
910 2nd Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1307 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1307 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1316 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1306 -& 1308 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1406 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1422 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Y	Visual, entire system was put in post 1978
1423 George St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
905 3rd Ave	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1008 & 1010 3rd Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1015 3rd Ave.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1014 & 1016 3rd Ave.	C	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1411 Electra	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
1216 3rd Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1411-1413 Gene St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1414-1416 Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1407-09 Gene St.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1309-1311 3rd Ave	С	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1313-1315 3rd Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1516 Kenny Dr.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1516 Kenny Dr.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1610 Kenny Dr.	C	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
1221 5th Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	
1221 5th Ave.	C	N	C	Other - describe in notes Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1221 5th Ave.	C	N	C	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
	C		С		Y		Y	Visual, entire system was put in post 1978
1226 5th Ave.		N		Other - describe in notes		Installed after lead ban	-	Visual, entire system was put in post 1978
1695 Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1701 Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
1701 Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
Hydrant 2nd Ave.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
Fire Hydrant	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Υ	Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978

WWTF Gene St.	С	N	С	Other - describe in notes	Υ	Installed after lead ban	Υ	Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978 Visual, entire system was put in post 1978
		N	С	Other - describe in notes	Y		Y	
WWTF Gene St. WWTF Gene St.	С	N N	C		Y	Installed after lead ban	Y	Visual, entire system was put in post 1978
WWIF Gene St.	С			Other - describe in notes		Installed after lead ban		Visual, entire system was put in post 1978
WWTF Gene St.	С	N	С	Other - describe in notes	Y	Installed after lead ban	Y	Visual, entire system was put in post 1978